

FARGO® DTC®1500

Windows Printer Driver

Release Notes

PLT-04544, A.1
September 2022



Copyright

© 2019 - 2022 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, DTC, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
September 2022	Release notes for 5.5.0.2.	A.1

A complete list of revisions is available in [Revision history](#).

1.1 Scope

These release notes provide information on the FARGO® DTC®1500 Windows Printer Driver version 5.5.0.2. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from a HID Global internal tracking system.

1.2 Supported operating systems

- Windows 7 x86/x64
- Windows 10 x86/x64
- Windows Server 2012
- Windows Server 2012 R2
- Windows Server 2016
- Windows Server 2019
- Windows Server 2022
- Windows 11

1.3 New features and enhancements

- Added the ability to apply resin scramble to both sides of the card (SICPI-1132).
- Modified the driver to allow for a 0 second sleep timer. With a sleep timer of zero the printer does not go to sleep (SICPI-1181)
- Updated the **About** screen with the current technical support contact information (SICPI-1129, TTP-13412)
- Allow white resin ribbon type to enable/disable resin scramble on all DTC drivers (SICPI-1172)

1.4 Resolved issues

- Resolved an occasional issue with Windows 10 (1903). When updating the driver, it no longer prompts users to stop the spooler service. (TTP-11917, SCSEP-77)

Revision history

Date	Description	Revision
September 2022	Release notes for 5.5.0.2.	A.1
July 2019	Release notes for 5.4.0.4.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2022 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-04544, Rev. A.1

Part of ASSA ABLOY