

HID® FARGO® DTC™5500LMX

Windows Printer Driver
Release Notes

Driver Version: 5.5.0.0
Driver Part Number: SFW-01047
PLT-04543, A.2
June 2023



Copyright

© 2019 - 2023 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated, or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, DTC, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
June 2023	Release notes for driver version 5.5.0.0.	A.2

A complete list of revisions is available in [Revision history](#).

1.1 Scope

These release notes provide information on the HID® FARGO® DTC™5500LMX Windows Printer Driver version 5.5.0.0. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from a HID Global internal tracking system.

1.2 Supported operating systems

- Windows 7 x86/x64
- Windows 10 x86/x64
- Windows 11
- Windows Server 2012 R2
- Windows Server 2016
- Windows Server 2019
- Windows Server 2022

1.3 New features and enhancements

- Added the ability to apply resin scramble to both sides of the card. (SICPI-1132)
- Modified the driver to allow for a 0 second sleep timer. With a sleep timer of zero the printer does not go to sleep. (SICPI-1181)
- Updated the **About** screen with the current technical support contact information. (SICPI-1129, TTP-13412)
- Allow white resin ribbon type to enable/disable resin scramble on all DTC drivers. (SICPI-1172)



Revision history

Date	Description	Revision
June 2023	Release notes for driver version 5.5.0.0.	A.2
January 2023	Release notes for driver version 5.4.0.7.	A.1
October 2019	Release notes for driver version 5.4.0.7.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2023 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-04543, Rev. A.2

Part of ASSA ABLOY